

Preventing Entanglement in Rotating Machinery

Key Safety Points:

- Use of Safety Guards: Ensure all rotating parts are properly guarded. Guards prevent accidental contact with moving parts, reducing the risk of entanglement.
- Clothing and Jewelry: Never wear loose clothing, jewelry, or anything that can get caught in machinery. Ensure long hair is tied back securely.
- Training: Workers must be trained to recognize entanglement hazards and understand the proper use of equipment.
- Proper Shutdown Procedure: If a part of the body or clothing gets caught, turn off the machine immediately and follow proper emergency response procedures.
- Stay Alert: Never work near rotating machinery when distracted or fatigued. Always stay focused on the task at hand to avoid accidents.